


AB-13.

Ⓐ Position of holes changed 4-24-11
 Ⓑ From $\frac{1}{4}$ " to $\frac{3}{16}$ " --- 4-25-11



Note - Clutch leather to be cut down to even thickness of $\frac{3}{16}$ " and lapped & glued to fit clutch cone. - Hair side must remain on outside of clutch.

Note - Do not punch holes

TUDHOPE MOTOR Co.	
ORILLIA CANADA	
CLUTCH FACING.	
DRAWING No. - AB-13	
MAT'L - LEATHER	
NO. REQUIRED - 1	
DRAWN BY - WJW	CHECKED BY -
TRACED BY - FLG	APP. BY -
DATE - 4-24-1911	